

Reference: Materials Science and Engineering, An Introduction, William D. Callister, Jr.

Chapter	Subject	Title	Page	Important figures	Included	Notes
9	Phase Diagram	Phase Diagrams	382		Included	
		9.1 INTRODUCTION			Included	
		Definitions and Basic Concepts	383	9.1	Included	
		9.2 SOLUBILITY LIMIT			Included	
		9.3 PHASES	384		Included	Diffusion
		9.4 MICROSTRUCTURE			Included	
		9.5 PHASE EQUILIBRIA	385		Included	
		equilibrium			Included	
		free energy			Included	
		phase equilibrium			Included	
		metastable			Included	
		9.6 ONE-COMPONENT (OR UNARY) PHASE DIAGRAMS	386	9.2	Included	phase diagram
		Binary Phase Diagrams			Included	
		9.7 BINARY ISOMORPHOUS SYSTEMS Possibly the easiest type of binary phase	387	9.3	Included	
		isomorphous			Included	
		9.8 INTERPRETATION OF PHASE DIAGRAMS	289		Included	
		Phases Present			Included	
		Determination of Phase Compositions			Concept Check 9.2, 9.3	
		tie line	290		Included	
		Determination of Phase Amounts			Included	
		lever rule			Included	
		9.9 DEVELOPMENT OF MICROSTRUCTURE IN ISOMORPHOUS ALLOYS	294		Included	
		Equilibrium Cooling		9.4	Included	
		Nonequilibrium Cooling	295		EXAMPLE PROBLEM 9.1, Important	
		9.10 MECHANICAL PROPERTIES OF ISOMORPHOUS ALLOYS	297		Included	
		9.11 BINARY EUTECTIC SYSTEMS	298		Included	
		solvus line			Included	
		solidus line			Included	
		liquidus line			Included	
		invariant point			Included	
		eutectic reaction		9.8	Concept Check 9.4, 9.5, EXAMPLE PROBLEM 9.2, 9.3	
		9.12 DEVELOPMENT OF MICROSTRUCTURE IN EUTECTIC ALLOYS	305	9.11, 9.12, 9.13	Included	
		eutectic structure	307	9.14, 9.15	Included	
		eutectic phase	308	9.16, 9.17, 9.18	Included	
		primary phase			Included	
		microconstituent			Included	
		9.13 EQUILIBRIUM DIAGRAMS HAVING INTERMEDIATE PHASES OR COMPOUNDS	311		Self reading, not included in exams	
		9.14 EUTECTOID AND PERITECTIC REACTIONS	313		Self reading, not included in exams	
		9.15 CONGRUENT PHASE TRANSFORMATIONS			Self reading, not included in exams	
		9.16 CERAMIC AND TERNARY PHASE DIAGRAMS	316		Self reading, not included in exams	
		9.17 THE GIBBS PHASE RULE			Self reading, not included in exams	
		The Iron-Carbon System	319	9.24, 9.25	Included, Very very important	
		9.18 THE IRON-IRON CARBIDE (Fe-Fe₃C) PHASE DIAGRAM			Included, Very very important	
		ferrite			Included, Very very important	
		austenite			Included, Very very important	
		cementite	320		Included, Very very important	
		Eutectic reaction for the iron-iron carbide system	321		Included, Very very important	
		Eutectoid reaction for the iron-iron carbide system			Included, Very very important	
		9.19 DEVELOPMENT OF MICROSTRUCTURE IN IRON-CARBON ALLOYS	322	9.26, 9.27	Included, Very very important	
		pearlite	323		Included, Very very important	
		Hypoeutectoid Alloys	324	9.28, 9.29	Included, Very very important	
		proeutectoid ferrite	325	9.30, 9.31	Included, Very very important	
		Hypereutectoid alloy	327	9.32, 9.33	Concept Check 9.8, EXAMPLE PROBLEM 9.4	
		Nonequilibrium Cooling	329		Included, Very very important	
10	Phase Transformations in Metals Development of Microstructure and Alteration of Mechanical Properties	9.20 THE INFLUENCE OF OTHER ALLOYING ELEMENTS		9.34, 9.35	Included, Very very important	
		Why Study Phase Transformations in Metals?	343		Self reading, not included in exams	
		10.1 INTRODUCTION	344		Self reading, not included in exams	
		Phase Transformations			Self reading, not included in exams	
		10.2 BASIC CONCEPTS			Self reading, not included in exams	
		10.3 THE KINETICS OF PHASE TRANSFORMATIONS			Self reading, not included in exams	
		Nucleation			Included	Definition only
		Homogeneous Nucleation	350		Self reading, not included in exams	
		Growth	352		Included	Definition only
		Kinetic Considerations of Solid-Solid Transformations			Self reading, not included in exams	
		10.4 METASTABLE VERSUS EQUILIBRIUM STATES	355		Self reading, not included in exams	
		Microstructural Property Changes in Iron-Carbon Alloys	356		Self reading, not included in exams	
		10.5 ISOTHERMAL TRANSFORMATION DIAGRAMS	356		Included	
		Pearlite		10.12, 10.13, 10.14	Included	
		Isothermal transformation diagram	358	10.14	Included	
		Coarse pearlite		10.15	Included	
		Fine pearlite	359		Included	
		Bainite	360	10.16, 10.17, 10.18	Included	
		Spheroidite	361	10.19, see also P362	Concept Check 10.1	
		Microalloy	362	10.20, 10.21	Concept Check 10.2	
		Athermal transformation (diffusionless)	364	10.22, 10.23, 10.24	EXAMPLE PROBLEM 10.2, Important	
		10.6 CONTINUOUS COOLING TRANSFORMATION DIAGRAMS	367	10.25, 10.26, 10.27	Included	
		Continuous cooling transformation (CCT) diagram	368		Included	
		10.7 MECHANICAL BEHAVIOR OF IRON-CARBON ALLOYS	370	10.29, 10.30	Included	
		Pearlite	370		Included	
		Spheroidite	373		Included	
		Bainite		10.31	Included	
		Microalloy		10.32	Concept Check 10.5	
		10.8 TEMPERED MARTENSITE	375	10.33, 10.34, 10.35	Included	
		Temper Embrittlement			Self reading, not included in exams	
		10.9 REVIEW OF PHASE TRANSFORMATIONS AND MECHANICAL PROPERTIES FOR IRON-CARBON ALLOYS	378	10.36, Table 10.2		

Alloy steel
Athermal transformation
Bainite
Coarse pearlite
Continuous cooling
diagram
Fine pearlite
Growth (phase particle)
Isothermal transformation
Kinetics
Martensite
Nucleation
Phase transformation
Plain carbon steel
Spheroidite
Supercooling
Superheating
Tempered martensite
transformation
transformation diagram
Transformation rate